

# Parts Required to Rebuild Kodak Prostar Processor Racks

ALL PRICES SUBJECT TO CHANGE WITHOUT NOTICE

## RACK # 1 DEVELOPER

PART NO.	DESCRIPTION OF AFTER MARKET PART	QUANTITY REQUIRED	UNIT PRICE	ORDER QUANTITY
170878	E-RING STAINLESS	12	\$ 0.50	
491648	ROLLER DOUBLE DR. TEFLON	2	\$18.00	
578610	.750 IDLER ROLLER TEFLON	1	\$18.00	
578612	GEAR SMALL ( INSIDE RACK)	3	\$ 1.50	
578613	ROLLER SINGLE DRIVE PLASTIC	5	\$14.00	
578617	ROLLER SINGLE DRIVE POLLY	3	\$18.00	
578623	.645 IDLER ROLLER POLLY	1	\$18.00	
578632	ROLLER SINGLE DRIVE TEFLON	5	\$18.00	
578635	.645 IDLER ROLLER TEFLON	1	\$18.00	
578694	FEED ROLLER	1	\$40.00	
878647	BEARING FILM FEED	1	\$ 5.00	
878658	SPACER	2	\$ 5.00	
878684	PULLEY FILM FEED	1	\$ 5.00	
913421	BUSHING	37	\$ 1.00	
KIT PRICE (INCLUDES ALL THE ABOVE PARTS)			\$375.50	

## RACK # 2 DEVELOPER

PART NO.	DESCRIPTION OF AFTER MARKET PART	QUANTITY REQUIRED	UNIT PRICE	ORDER QUANTITY
170878	E-RING STAINLESS	11	\$ 0.50	
491648	ROLLER DOUBLE DRIVE TEFLON	2	\$18.00	
578610	.750 ROLLER IDLER TEFLON	2	\$18.00	
578612	GEAR SMALL (INSIDE RACK)	5	\$ 1.50	
578613	ROLLER SINGLE DRIVE PLASTIC	10	\$14.00	
578617	ROLLER SINGLE DRIVE POLLY	3	\$18.00	
578623	.645 ROLLER POLLY	1	\$18.00	
578635	.645 ROLLER TEFLON	2	\$18.00	
878647	BEARING FILM FEED	1	\$ 5.00	
878658	SPACER	4	\$ 5.00	
878684	PULLEY FILM FEED	1	\$ 5.00	
913421	BUSHING	41	\$ 1.00	
KIT PRICE (INCLUDES ALL THE ABOVE PARTS)			\$364.00	

### RACK # 3 WASH

PART NO.	DESCRIPTION OF AFTER MARKET PART	QUANTITY REQUIRED	UNIT PRICE	ORDER QUANTITY
170878	E-RING STAINLESS	11	\$ 0.50	
491648	ROLLER DOUBLE DRIVE TEFLON	2	\$18.00	
578610	.750 IDLER ROLLER TEFLON	2	\$18.00	
578612	GEAR SMALL ( INSIDE RACK)	5	\$ 1.50	
578613	ROLLER SINGLE DRIVE PLASTIC	13	\$14.00	
578623	.645 IDLER ROLLER POLLY	1	\$18.00	
578635	.645 IDLER ROLLER TEFLON	2	\$18.00	
878658	SPACER	4	\$ 5.00	
913421	BUSHING	40	\$ 1.00	
KIT PRICE (INCLUDES ALL THE ABOVE PARTS)			\$341.00	

### RACKS # 4 AND # 5 FIXER

PART NO.	DESCRIPTION OF AFTER MARKET PART	QUANTITY REQUIRED	UNIT PRICE	ORDER QUANTITY
170878	E-RING STAINLESS	11	\$ 0.50	
578610	.750 IDLER ROLLER TEFLON	2	\$18.00	
578612	GEAR SMALL ( INSIDE RACK)	5	\$ 1.50	
578613	ROLLER SINGLE DRIVE PLASTIC	10	\$14.00	
578617	ROLLER SINGLE DRIVE POLLY	3	\$18.00	
578623	.645 IDLER ROLLER POLLY	1	\$18.00	
578635	.645 IDLER ROLLER TEFLON	2	\$18.00	
578642	ROLLER DOUBLE DRIVE PLASTIC	2	\$14.00	
878658	SPACER	4	\$ 5.00	
913421	BUSHING	40	\$ 1.00	
KIT PRICE (INCLUDES ALL THE ABOVE PARTS)			\$ 345.00	

## RACK # 6 WASH

PART NO.	DESCRIPTION OF AFTER MARKET PART	QUANTITY REQUIRED	UNIT PRICE	ORDER QUANTITY
170878	E-RING STAINLESS	13	\$ 0.50	
578610	.750 ROLLER IDLER TEFLON	1	\$18.00	
578612	GEAR SMALL ( INSIDE RACK)	7	\$ 1.50	
578613	ROLLER SINGLE DRIVE PLASTIC	13	\$14.00	
578623	ROLLER IDLER POLLY	1	\$18.00	
578635	ROLLER SILICONE IDLER	1	\$18.00	
578642	ROLLER DOUBLE DRIVE PLASTIC	2	\$14.00	
878658	SPACER	4	\$ 5.00	
879281	SPRING ( TOGGLE ARM)	2	\$10.00	
879996	TOGGLE ARM	2	\$14.00	
913420	.770 ROLLER SQUEEGEE	2	\$50.00	
913421	BUSHING	42	\$ 1.00	
KIT PRICE (INCLUDES ALL THE ABOVE PARTS)			\$445.00	

## DRYER RACK

PART NO.	DESCRIPTION OF AFTER MARKET PART	QUANTITY REQUIRED	UNIT PRICE	ORDER QUANTITY
170878	E-RING STAINLESS	19	\$ 0.50	
578610	.750 ROLLER IDLER TEFLON	1	\$18.00	
578612	GEAR SMALL ( INSIDE RACK)	10	\$ 1.50	
578623	ROLLER IDLER POLLY	5	\$18.00	
6C3972	ROLLER SINTERED NYLON	4	\$45.00	
913421	BUSHING	20	\$ 1.00	
KIT PRICE (INCLUDES ALL THE ABOVE PARTS)			\$300.50	

Name:

Email:

Company:

Address:

City:

State:

Zip:

Country:

Phone No:

FAX No:

Special Instructions:

Please email this order form to [mike@worldmicrographics.com](mailto:mike@worldmicrographics.com)  
or fax toll free to 877-619-6025